

Errata for PCI 3.0

This paper lists the known errata for the PCI Local Bus Specification Revision 3.0. If you have found others, please mail them to techsupp@pcisig.com.

Figure 5-7 requires the following correction.

- Datum C (in the card, top view) needs to be moved from the back side of the card to the component side of the card.